Maryland Historical Trust State Historic Sites Inventory Form MARYLAND INVENTORY OF HISTORIC PROPERTIES

Survey No. B-4402

Magi No.

DOE __yes __no

1. Naı	ne (indicate pro	eferred name)				
historic		13 West Saratoga	Street			
and/or commo		nt, #411 Aquaria			***************************************	
	ation #413 Bech	tel Plating Co.				
street & number 409-411-		113 W. Saratoga Street			not for publication	
city, town	Baltimore	vicinity of	congressional dis	strict	Seventh	- Seattlin
state	Maryland	county	Balti	more		
3. Cla	ssification					
Category district X building(s structure site object	Ownership public private both Public Acquisition in process being considered XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	Status X occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted no	Present Use agriculture X commercia educationa entertainm governmen industrial military	l I ent . it .	museum park private residen religious scientific transportation other:	ice
4. Ow	ner of Prope	rty (give names a	nd mailing add	resses	of <u>all</u> owners)	
name	see attached	sheet				
street & numb	• er	telephone no.:				
city, town		state	and zip code			
5. Loc	ation of Leg	al Descripti	on			
courthouse, re	gistry of deedspagtimor	e City Courthous	se		liber	
street & numb	er 100 N. C	alvert Street, I	Room 610		folio	
city, town	Baltimor	e		state	MD	
6. Rep	oresentation	in Existing	Historical	Survey	7S	
title						
date			federal	state	county	oca
ository for	survey records					
city, town				state		

7. Description

Condition
excellent
good

_ fair

__ deteriorated __ ruins __ unexposed Check one
unaltered
altered

Check one
X_ original site

__ moved date of move

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

Resource Count: 3

This circa 1850-1860 Italianate brick commercial block building faces north on West Saratoga Street and abuts a partywall structure to the east and a modern alley to the west. The building is four stories high and six bays wide. It is divided into three two-bay units, each painted a different color. Each store front has different architectural treatments, but the upper stories are similar and there is no seam in the brick work between the units.

The first story of #409 is composed of a large display window that almost fills the facade. The display window is boxed and projects beyond the plane of the facade. The plate glass is modern, but the opening and window surrounds are original. The base of the windows have molded trim of Greek ovolo, two fillets, cove, bead, fillet, back band bead and fillet. The display base has low, five- panelled backdrop behind it. The entrance is to the far western edge of the second bay and is flush with the facade. The entrance is reached by six steps. Through the glass door one can see that there is a door to the east that opens into the first floor and a stair hall to the south that runs straight up the west wall. A pent roof covers the bow of the display window and shelters the entrance.

The first story of #411 contains two recessed entrances in the first bay and a display window in the second. The glass doors have wood surrounds. The first door leads to an enclosed vestibule with a landing that leads down the hall to a stair that rises along the The second door leads to the first floor back south wall. commercial space. Recessed field panels line the walls and soffit of the recessed entrance. The floor is tiled in white hexagonal The display window projects slightly beyond the plane of The large plates of glass are modern, but the tiles. overhanging cornice and sign board above the opening are original. the facade. The cornice extends across the width of the facade and forms a porch over the recessed entry. The profile of the cornice is fillet, two ogees and two fillets. A series of five transom windows run across the top of the cornice. The pilasters are divided by pilasters and surmounted by an ornate cornice of fillet, ogee, two fillets, two back bands, a quarter round, cove, back band, cove, and fillet trim.

The first story of #413 has been resurfaced with black vitrolite panels that border the display window and east section of the wall. The display window almost fills the two bays, with the entrance in far western side of the second bay. The door is set in an angled recess. The door is glass with wood surrounds and it has a narrow transom. A metal sigh board runs across the facade under the second story windows. Remnants of the original door surrounds and window cornice remain. A metal security grill is bolted over

B-4402 409-413 West Saratoga Street Baltimore, MD Section 7 Description 7.1

the glass.

The second, third, and fourth stories are stacked versions of each other, with the height of the windows decreasing as the building rises. Six windows are evenly spaced across each story. The second story has 1/1 sash windows in the first two bays, 6/1 sash with infill panels where the sash is too short for the opening in the third and fourth bays, and 6/9 sash in the fifth and sixth bays. The windows have stone sills and the lintels are embellished by dentil courses.

The windows in the third and fourth stories are two 1/1 sash, and four 6/6 sash. The sills are stone. There are no decorative lintels.

The projecting cornice is supported by 21 large brackets with foliated pendants that drop down and lap over a stringcourse of raised molding. A projecting brick stringcourse runs below the cornice.

The west wall facing the alley is blank brick. A back building extends from the rear of #413 on the alley. It consists of a three-bay, four-story addition and a four-bay three-story addition. The four-story addition is set in one bay from the edge of the main building. It has a corbelled brick cornice. The three-story addition has an L plan, running two-bays long and then jutting out one bay to directly front the alley for an additional two bays. The south wall is blank.

The interiors of the front rooms of #409 and #413 have pressed tin ceilings and crown molding. #413 is divided into three rooms, the front has shelves and cases lining the walls, a middle room that appears to hold the stair case, and a back room that appears to be work space. #411 was not accessible.

Specific dates

Builder/Architect unknown

check: Applicable Criteria: A B X C D
and/or
Applicable Exception: A B C D E F G

Level of Significance: __national __state __xlocal

Prepare both a summary paragraph of significance and a general statement of history and support.

This six-bay, four-story building is a typical example of commercial block construction along Saratoga Street during the third quarter of the nineteenth century. The first story would have been used for sales or display area and the upper stories would have been used as dwellings or office space. The different first-story doorway treatments gave a bit of individuality to each of the repetitive units. The upper stories are, however, all identically treated and with the continuous cornice give an imposing, massive air to the building. Overall the building is a 1850s aesthetics example of the circa of mixed-use architecture. The rather severe facade is punctuated by decreasing window heights as the building rises. The top stories have the least embellished lintels; although the lower stories lintels and the cornice are typically Victorian with projecting eaves, dentil courses and scrolled brackets. Sheer size was also an important part of the design.

The presence of shops and quarters indicates the mixed residential and commercial character of this Baltimore neighborhood in the late nineteenth century. The first story on each unit has been altered, but the presence o multiple entrances in two of the units indicates that these buildings were probably combination shop-houses or shop-offices intended for several tenants. One unit (#413) however has its staircase in the middle of the plan, indicating a single tenant use. The storefronts retain elements of their original commercial styling. Architectural historian Richard Longstreth writes that "shop-houses prevailed in emerging commercial centers of cities and towns alike through the early decades of the 19th century. Examples can still be seen in areas that have not experienced radical change, even though the shopfronts themselves have almost always been altered. . . upper section retaining a domestic character." particular example, the both the commercial and the residential nature of the applicable stories prevailed through to the present century.

¹ Longstreth, Buildings of Main Street, p. 24.

Richard Longstreth, The Buildings of Main Street (Washington: Preservation Press, 1987)

10. Ged	graphical Data							
Acreage of nomin Quadrangle name UTM References	Daltimore Fact Ouad	š	Quadrangle scale					
Zone Easting	g Northing	B Zone East	ing Northing					
C		D						
Verbal boundary description and justification List all states and counties for properties overlapping state or county boundaries								
state	code co	ounty	code					
state	code co	ounty	code					
11. For	m Prepared By							
name/title	Diane Shaw, Architectural	. Historian						
name/title organization	Diane Shaw, Architectural	. Historian	December 21, 1991					
	<u> </u>		201 206 4866					

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

MARYLAND HISTORICAL TRUST DHCP/DHCE 100 COMMUNITY PLACE CROWNSVILLE, MD 21032-207

301-514-7600

B-4402 Owners of Property

#409 West Saratoga Street Stephen Corp. 313 N. Howard St. Baltimore MD 21201

#411-413 West Saratoga Street
Investors Management
2275 Fairground Road
W. Friendship MD 21794

B-4402 409-413 West Saratoga Street Baltimore, MD Section 8 Significance 8.1

The first-story facades are good examples of nineteenth-century storefronts. The large plate glass windows set in wood architraves, often with transoms, provided the much desired display space and interior illumination. The slightly inset entrances accentuated the projecting image of the display window. #409 is valuable for its retention of the wood panelled backboard to the display case and interior pressed tin ceilings. #411 retains its typical transoms. #413 retains the pressed tin ceilings and three-room plan. It is unusual in that it has the staircase in the second room, and thus it there was no segregation of access in this unit as there were in the other units.

COMPREHENSIVE PLAN DATA

HISTORIC CONTEXT:

Geographic Organization: Piedmont

Historic Period Themes:
Architecture
Economics

Resource Type:
Building

Historic Environment: Urban

Historic Function and Use:

Commercial/Residential


Known Design Source: None

SOURCES AND IS NOT AN AUTHENTIC SURVEY.

SCALE /"= 50'-0"

.. DATE MAY 1983

B-4402 409-411-413 W. Saratoga Street Block 05**9**5 Lot 025 Baltimore City





8-4402 409-413 W. Saratoga St Baltimore MD Dane Shaw maryland SHPO Facade, NW elevation



B-4402 409 W. Savatoga St. Baltimore mo Drane Shaw maryland SHPO Facade, detail



B-440Z 411 W Saratoga St. Baltimore MD Drane Shaw maryland SHPO Facade, detail



B-440Z 413 W. Saia toga St. Baltemore MD Drane Shaw manyland SHPD Facade, detail